

Safata District



Dangerous corner eroding behind spring.



Blocked culvert on Main South Coast Road. Left photo inland side – right photo seaward side.