

Salelavalu



Large tree being undermined At Salelavalu.



Work road intersection with Main Road showing scour along left hand side.