

### Faasaleleaga 1 District



Blocked drain behind road at Saletagaloa.



Flood area behind road at Vai'afai caused by culvert outlet invert being lower than surrounding ground levels. Exposed galvanised water pipe to be replaced by new PVC pipe under the EU Rural Water Supply Project.